# How to Measure An Angle Using the SmartMicroScope 5M on Mac

Connect the SmartMicroScope 5M to the USB port and then open the software

Place the SmartMicroScope 5M on a ruler and adjust the focus knob until the image is sharp.

1. Using the function keys at the side of the Viewer, Click on the Measurement Tool

2. From here, The Measurement Window will Open

3. Click the Calibrate Tab

4. Change the Reference Unit to appropriate measurement (inch, mm, mil)

5. Change the Reference Size to the appropriate number

6. Using the mouse click on the Left side of the ruler and drag to the right to the appropriate distance

7. Release the mouse and your calibration is complete

SMARTSCHOOL systems

1-866-722-2051   www.smartschoolsystems.com

How to Measure An Angle Using the SmartMicroScope 5M on Mac

8. Click on the Measure Tool

9. Choose the Measure Mode: ANGLE

10.

11. Place your image under the SmartMicroScope

12. Place your mouse at the vertex (corner) of your image.

13. Click at the vertex and drag down one leg of the angle.

14. Release the mouse button and move the cursor to the other leg of the angle and click.

15. The measurement is displayed

To Save your image click the Save Tool   or Print with the Print tool

16. After finishing the measurement click the measurement Tool   to return to viewer

*****Technical support, please call 281-312-1297, 1-866-722-2051 or email support@smartschoolsystems.com

SMARTSCHOOL systems

1-866-722-2051   www.smartschoolsystems.com